

### 1 Clean surfaces




Before applying tape, remove dust, grease and dirt with a cloth and alcohol, or tack cloth.

### 2 Smoothing



Apply tape and remove ripples, air pockets and bubbles with a smoothing tool.

### 3 Coating



Properly applied, the PTFE tape will protect non-target surfaces from the extreme heat of the coating process.

### 4 Remove Tape



Tape is easily removed with little or no residue left behind. Clean any residue with a soft cloth and alcohol (if needed).